

Jorgensen Forge Outfall Site Quality Assurance (QA) Daily Report Form

Date	9/23/2015
Name	Jake Williams
Time onsite	0700-0900
Weather (temp, conditions, wind)	55 degrees F, clear
Work performed today	Finished backfill of the remaining trench. Levelled out soil. Continued to demobilize site. Work completed today.
Problems encountered?	- Smoking in excavator. Not wearing proper PPE at all times.
Notes	- Work concluded for now. Could be future work done here.
Issues for followup	- N/A
Photographs taken?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>

USEPA SF



1500291

Name: Jake Williams

Title: Chemist

Date: 23 September 2015

Photos:

Photo 1: Starting backfill



Photo 2: Trench during backfill



Photo 3: Completed backfill and leveling soil out



Photo 4: Removing final steel plate



Photo 5: Completed backfill and final work

